


Water features on sites monitored

- 9 timber sales had lakes
- □ 39 timber sales had streams
- 29 timber sales had wetlands





BMP Application

	Federal	Industrial
■ BMP applied correctly	20.6%	24.0%
■ BMP applied but incorrectly	0.3%	0.4%
■ BMP not applied	0.7%	1.2%
□ Insufficient information to rate	1.1%	1.2%
■ BMP not applicable to the site	77.0%	73.2%


BMP Effectiveness

	Federal	Industrial
■ No adverse impact	21.1%	24.6%
■Minor short-term impact	0.2%	0.4%
■Minor long-term impact	0.4%	0.6%
□Major short-term impact	0.0%	0.0%
□Major long-term impact	0.0%	0.0%
■ Effectiveness rating not applicable	78.0%	74.3%

What's to come?

- □ Statistical analysis of data
- Write report
- Share results with landowners who had timber sales monitored

■ To be completed early spring 2007



What did we do?

- Completed RMZ and Stream Crossing portions of the two protocols
- 4 teams, each team got experience with both portions of each protocol



Why did we do it?

- Committee members get an idea of what the USFS Regional Monitoring Protocol is like
- Compare the two methods to determine if we may want to use the USFS protocol for future BMP monitoring efforts





General Results – RMZ

- WI protocol
 - Main "issues" with harvest:
 - Location of road and use of equipment near stream
 - Harvesting within RMZ
- USFS regional protocol
 - Main "issues" with harvest:
 - □ No major issues identified



Differences between protocols

- WI protocol identifies that road is too close to stream and equipment was used in "no equipment zone"
- Because no soil is seen moving in the RMZ, the USFS protocol doesn't identify the road/equipment as a problem

General Results - Stream Crossing

- WI protocol
 - Main "issues" with harvest:
 Installation and maintenance of culvert
- USFS regional protocol
 - Main "issues" with harvest:
 - Soil moving in RMZ (but not reaching stream)
 - Culvert width is less than bankfull width
 - Evidence of scouring/sedimentation at crossing



Differences between protocols

- Both identify that there are problems with the installation and maintenance of the culvert.
- WI protocol identifies that BMPs weren't followed, but doesn't identify specific problems that have resulted because BMPs weren't followed
- USFS protocol identifies what issues are occurring because of the culvert problem (soil moving into stream)

WI Protocol

Stream Crossing BMPs that generated different evaluations

- □ Disruption of fish/aquatic life movement
- Place fill over culvert higher than road approach
- Use riprap around culvert inlet (fabric under riprap if permanent culvert)
- Keep culverts clear and free of debris

USFS Regional Protocol Stream Crossing questions that generated different responses

- □ Distance soil moved
- Evidence that soil moved
- Road bearing capacity improvements
- Soil movement in Approach A Inside Ruffer
- Evidence that sediment reached water body
- □ Preponderant type of sediment

USFS Regional Protocol Stream Crossing questions that generated different responses (cont)


- Sediment continuing next storm
- Distance soil moved as percent of buffer width
- □ Age of crossing structure

Is this a problem?

■ Both protocols tend to have a certain amount of inconsistency with how different teams rate/answer different items

Is this a problem?

- This will always be an issue, but because USFS protocol generates specific and quantitative data, this inconsistency between teams could generate very different results for one timber sale
 - Same is true for WI protocol but less specific results are being generated
 - Overall may mean that results will always need to be taken as subjective and as a best guess of on the ground conditions





2006 BMP Monitoring Exercise 22 sales were monitored with both the WI BMP monitoring protocol & the USDA FS Regional monitoring protocol Goal was to compare the methods and results of each method

Option 1: WI Method

· What was the effect of BMP application?

• Used since 1995

6-member teamsQualitative data

Was BMP applied?

Future Monitoring Options Option 1: Continue using existing Wisconsin BMP monitoring protocol Option 2: Use USDA FS Regional BMP monitoring protocol Option 3: Use a hybrid of Wisconsin BMP & USDA FS BMP monitoring protocol





Option 2: FS Regional Method

- Developed by ME FS and USDA FS
- 2-member teams or larger
- Collect data on hand-held recorder
- Uses a tree structure for questions
- Quantitative and qualitative data
- Were BMP principles satisfied?

Option 2: Advantages

- Other state in NA are using
- Less subjective
- Easy of data entry
- Automated report generation
- Cost savings

Option 2: Disadvantages

- Investment in equipment
- Not an "approved" software
- Programming glitches
- Comparing 1995 2006 data
- May not monitor in 2007 or may have smaller sampling size

Option 3: WI / FS Hybrid

- Combine best of both worlds
- 2-member teams or larger
- Collect data on hand-held recorder
- Use a tree structure for questions
- Quantitative and qualitative data
- Focus on specific BMPs & principles

Option 3: Advantages

- Fit to Wisconsin's needs
- Compare to historic data
- Allow consolidation with other NA states
- Introduce less subjective questions
- Data entry
- Automated report templates
- Cost savings


Option 3: Disadvantages


- Investment to develop program
- Investment in equipment
- May not monitor in 2007 or may have smaller sampling size

















Macroinvertebrate Index of Biotic Integrity (IBI) Weigel, B. 2003. Development of stream macroinvertebrate models that predict watershed and local stressors in Wisconsin. Journal of the North American Benthological Society 22: 123-142. Macroinvertebrate multi-metric IBIs use several assemblage attributes to indicate stress on the biota: Species richness % Nutrient tolerant % Sediment tolerant % Mayflies, Stoneflies, & Caddis flies % Feeding guilds












































Sale Identification Process



- 381 sales open on July 1, 2006
- 278 of those were sold
- Random numbered the 278 sales
- Contacted first 100 sales to see if any harvesting had occurred yet
- 41 sales had started harvesting or completed harvesting
- 30 first sales of the 41 sales were visited

Background Information Map Harvesting dates Sale acreage Harvest equipment Clear and process. Some maintenance is in process to call are made of with course, pair. This is a 2nd thering. Clear and species. CEEFF pair, pair, pair, as well be presented. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Delta personnel. Clear and species. Some maintenance is required for all species. Clear and species. Some maintenance is required for all species. Clear and species. Some maintenance is required for all species. Clear and species. Some maintenance is required for all species. Clear and speci

Equipment

- Level
- Soil Pentrometer
- Folding Ruler
- Small Shovel
- GPS
- Camera



Roads, Landings, & Primary Skid Trails

- Area
- New vs. Existing
- Removed from production?
- Active erosion?
- Altered drainage?



Transects

- Coordinates
- Slope
- % Bare soil
- Soil texture
- Soil compaction every 100 feet



Ruts & Gullies

- Roads, landings, primary skid trails & transects
- Total length
- Length deeper than 6 inches
- Length deeper than 10 inches
- Total depth
- Location and orientation
- Cause and age



Not Recorded if...

- Depth was less than 6 inches in entirety
- Length was less than 5 feet in entirety
- Did not bisect a transect in harvest area



Timber Sale Property Types

- 20 sales on State Forests
- 4 sales on Wildlife Areas
- 2 sales on Scenic Waters Areas
- 1 sale on a Fishery Area
- 1 sale on a State Park
- 1 sale on a Natural Resources Area
- 1 sale on a Wild River

State Forests - 20 Sales

• American Legion – 2



State Forests – 20 Sales

- American Legion 2
- Black River 5



State Forests - 20 Sales

- American Legion 2
- Black River 5
- Brule River 1



State Forests - 20 Sales

- American Legion 2
- Black River 5
- Brule River 1
- Flambeau River 4



State Forests – 20 Sales

- American Legion 2
- Black River 5
- Brule River 1
- Flambeau River 4
- Gov. Knowles 3



State Forests - 20 Sales

- American Legion 2
- Black River 5
- Brule River 1
- Flambeau River 4
- Gov. Knowles 3
- N. Highland 5




Wildlife Areas - 4

- Beaver Brook
- Chief River
- Fish Lake
- Wood County



Other Sales - 6

- Chippewa Flowage Scenic Waters Area
- Turtle Flambeau Scenic Waters Area
- Beverly Lake Fishery Area
- Gov. Thompson State Park
- Menominee Natural Resource Area
- Pine-Popple Wild Rivers



Harvesting Status

- 10 sales in progress
 - Averaged over 50% of sale completed
- 20 sales completed
 - Averaged 5 months since sale completed



Sale Size


- Averaged 90 acres
- Largest = 282 acres
- Smallest = 22 acres



No Ruts or Gullies Observed



- Did not observe ruts or gullies on 9 sales
- 7 were on sandy soils
- 2 were on heavier soils



Observed Ruts or Gullies




- Observed ruts or gullies on 21 sales
- 2 sales had excessive rutting
 - 1 was caused by harvesting equipment
 - 1 was a mix of harvesting equipment & off-road vehicles
- 19 sales has ruts/gullies, but not excessive
 - Caused primarily by harvesting equipment

The BMP Field Manual

Editing & Updating Options

BMP Advisory Committee Meeting December 2006





There are only 400 left at our warehouse!

It's the perfect time to do some updating

Past Changes to the Manual

- □ Published in March 1995
- □ Reprinted in August, 1997 and May, 2003
- Changes made were minor grammatical edits
- Most changes made in appendix A, "Sources for Help", and Appendix B, "Regulations"
- BMPs themselves have not changed

Current Goals

- Make the manual more widely used and more user-friendly
- Keep the BMPs as is (per our June Advisory Committee meeting discussion)
- Update the BMPs after BMP monitoring protocol effort is completed (per our June Advisory Committee meeting discussion)
- Begin work on a Forestry BMP Guidebook (modules that compliment BMP training)

Suggestions for updates

- Correct spelling and grammatical errors
- Improve manual design and illustrations (add color!)
- □ Update statututes/regulations
- Update permit information
- Add background information to explain BMP issues better
- Clarify definitions
- □ Add "Practices to Avoid"